L Number	Hits	Search Text	DB	Time stamp
-	6	("4990887" "5139115" "6023221").pn.	USPAT;	2004/10/22 16:02
		(1330007 3133113 0023221 7.5/	US-PGPUB;	200 1/10/22 10:02
			EPO; JPO;	
			DERWENT	
-	8	("4357594" "4663609" "4987405" "4990887" "5139115"	USPAT	2004/10/21 13:21
		"5231373" "5394326" "5712617").PN.		
-	2	6023221.URPN.	USPAT	2004/10/21 13:21
-	403	(340/441).CCLS.	USPAT;	2004/10/21 13:27
			US-PGPUB;	
			EPO; JPO;	
į			DERWENT	
} -	42	((340/441).CCLS.) and (((warning hazard emergency) adj2	USPAT;	2004/10/21 13:40
\		light\$3) flasher\$1 blinker\$1 winker\$1)	US-PGPUB;	
			EPO; JPO;	
1			DERWENT	
-	2	(((340/441).CCLS.) and (((warning hazard emergency) adj2	USPAT;	2004/10/21 13:29
		light\$3) flasher\$1 blinker\$1 winker\$1)) and (engine near4 (stall	US-PGPUB;	
		failure))	EPO; JPO;	
			DERWENT	
-	8	("3699415" "3882452" "4878042").pn.	USPAT;	2004/10/21 13:50
			US-PGPUB;	
			EPO; JPO;	
	5040	(/240/425 5 420 420 462 464 460 474)	DERWENT	0004440404
-	5940	((340/425.5,438,439,463,464,468,471) or	USPAT;	2004/10/21 14:41
		(362/499,540,542)).CCLS.	US-PGPUB;	
			EPO; JPO;	
	12	///240/425 5 429 420 462 464 469 471) or	DERWENT	2004/10/21 15:10
-	13	(((340/425.5,438,439,463,464,468,471) or (362/499,540,542)).CCLS.) and (engine adj (stall failure)) and	USPAT; US-PGPUB;	2004/10/21 15:19
		((hazard emergency warning) adj (light\$3 signal\$4))	EPO; JPO;	
		((mazard emergency warming) adj (mgmt\$5 signal\$4))	DERWENT	
_	3	(power adj bypass) adj relay	USPAT;	2004/10/22 08:09
	J	(power adj bypass) adj relay	US-PGPUB;	200 1/ 10/22 00:03
			EPO; JPO;	
			DERWENT	
-	114	(power adj relay) and ((hazard caution warning emergency) adj	USPAT;	2004/10/22 08:18
		(light\$4 flasher blinker winker))	US-PGPUB;	
			EPO; JPO;	
			DERWENT	
-	66	1 (() = 1 = 1 = 1 = 1 = 1 = 1 = 1 = 1 = 1 =	USPAT;	2004/10/22 08:11
		adj (light\$4 flasher blinker winker))) and (vehicle automobile)	US-PGPUB;	
			EPO; JPO;	
		(UC 4357504 A . UC 6507724 A . UC 4065540 A	DERWENT	2004/40/22 22 22
-	14	(US-4357594-\$ or US-6583734-\$ or US-4965549-\$ or	USPAT;	2004/10/22 09:25
		US-4878042-\$ or US-3882452-\$ or US-3699514-\$ or	US-PGPUB;	
		US-5602462-\$ or US-5164636-\$ or US-4843370-\$ or US-4807101-\$ or US-3771122-\$ or US-6744359-\$).did. or	DERWENT	ļ
		(US-20020158755-\$).did. or (US-4878042-\$).did.		
_	21864	flashers blinkers winkers ((caution hazard warning emergency)	USPAT;	2004/10/22 09:29
	21004	adj light\$4)	US-PGPUB;	200 1/10/22 03.23
		and using it	EPO; JPO;	
			DERWENT	
_	116	(flashers blinkers winkers ((caution hazard warning emergency)	USPAT;	2004/10/22 09:35
		adj light\$4)) and (engine adj (stall failure))	US-PGPUB;	
			EPO; JPO;	
			DERWENT	
-	156	(flashers blinkers winkers ((caution hazard warning emergency)	USPAT;	2004/10/22 09:35
		adj light\$4)) and alternator and starter	US-PGPUB;	
			EPO; JPO;	
			DERWENT	

-	5637	((701/29) or (307/9.1,10.1,10.8,10.6,10.7)).CCLS.	USPAT; US-PGPUB;	2004/10/22 16:05
-	41	(((701/29) or (307/9.1,10.1,10.8,10.6,10.7)).CCLS.) and (engine adj (stall failure))	EPO; JPO; DERWENT USPAT; US-PGPUB; EPO; JPO;	2004/10/22 16:07
-	496	(((701/29) or (307/9.1,10.1,10.8,10.6,10.7)).CCLS.) and (((hazard caution warning emergency) adj (light\$3 signal\$3)) flasher winker blinker)	DERWENT USPAT; US-PGPUB; EPO; JPO;	2004/10/22 16:09
-	355	(((701/29) or (307/9.1,10.1,10.8,10.6,10.7)).CCLS.) and (power near3 relay)	DERWENT USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/22 16:09
-	63	((((701/29) or (307/9.1,10.1,10.8,10.6,10.7)).CCLS.) and (power near3 relay)) and (((hazard caution warning emergency) adj (light\$3 signal\$3)) flasher winker blinker)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/22 16:09